

SECRET

OUT58228

1966 APR 14 21 33Z

SECRET 142123Z

6919

25X1

15 APR 1966

1. CAMERA NUMBER B-7 WAS USED IN MISSION 8085 FLOWN ON 12 APRIL 1966. PROCESSING WAS ACCOMPLISHED BY BARKSDALE.

2. ORIGINAL NEGATIVE:

A. EXPOSURE WAS ADEQUATE. THE RESOLUTION IS GOOD WHERE NOT DEGRADED BY CLOUDS.

B. 9R SIDE: MINOR ROLLER CHATTER IS PRESENT THROUGHOUT THE MISSION ON THE INBOARD EDGE, AND INTERMITTENTLY PRESENT ON THE OUTBOARD EDGE. THE VERTICAL DOT POSITION INDICATOR IS BLOOMED. PINHOLES, EMULSION DEFECTS, AND EMULSION BLISTERS ARE PRESENT INTERMITTENTLY THROUGHOUT. A MANUFACTURER'S SPLICE IS LOCATED IN THE FORMAT OF FRAME 1098 WITH ASSOCIATED EMULSION LIFTS ON FRAMES 1097 THROUGH 1099. THE MISSION WAS FLOWN ON 12 APRIL 1966 BUT THE 9R SIDE WAS TITLED 21 APRIL 1966.

C. 9L SIDE: EDGE STATIC AND EDGE FOG IS PRESENT ALONG THE OUTBOARD EDGE THROUGHOUT THE MISSION. THERE ARE MANY ROWS OF MINUS DENSITY DOTS IN FRAME 2. ONE OF THESE ROWS IS NOTED INTERMITTENTLY THROUGH FRAME 1700. THEY ARE 1.5" APART AND 3.1" FROM THE OUTBOARD EDGE. THERE ARE ABRASION MARKS ON THE EMULSION SIDE OF FRAMES 1800 THRU 1872. THESE APPEAR TO BE CAUSED BY DRAGGING OR PULLING THE FILM ACROSS A ROLLER. A MANUFACTURING SPLICE IS LOCATED IN FRAME 1181. A PAPER BREAKDOWN SPLICE WAS NOTED BETWEEN FRAMES 311/312.

Advance copy
Sanitized

GROUP 1
Excluded from automatic
downgrading and
declassification

SECRET

D. BOTH SIDES: ULTRASONIC SPLICES WERE USED FOR THE FIRST TIME DURING BREAKDOWN OF THE MISSION. MANY OF THESE SPLICES WERE ALSO COVERED WITH TRANSPARENT TAPE, PROBABLY FOR REINFORCEMENT. ONE OF THE SPLICES ON THE 9L FILM PARTED DURING FILM EVALUATION. THE LAST TITLED FRAME IS 2519.

E. THERE WERE NO MAJOR CAMERA OR PROCESSING MALFUNCTIONS.

3. POSITIVE:

A. PI SUITABILITY WAS FAIR DUE TO ATMOSPHERIC DEGRADATION.

B. PRINTING AND PROCESSING WERE GOOD.

C. CLOUDS OBSCURED OR DEGRADED APPROXIMATELY 55 PERCENT OF THE MISSION.

S E C R E T

/END OF MESSAGE/